FY			
Location	Ward	Spot Coolers Request	Window Unit Request
BEERS ELEMENTARY SCHOOL 3600 ALABAMA AVENUE SE	7		1
ROOSEVELT HIGH SCHOOL 4301 13TH STREET NW	4	53	82
J.O. WILSON SWING SITE 810 26th Street Northeast	5		5
JACKSON - REED HIGH SCHOOL 3950 CHESAPEAKE STREET NW	3	3	
Tubman ES @ Old Banneker 800 EUCLID STREET NW	1		5
Thomas @Kenilworth 1300 44TH STREET NE	7		1
HART MIDDLE SCHOOL 601 MISSISSIPPI AVENUE SE	8		1
WATKINS ELEMENTARY SCHOOL 420 12TH STREET SE	6	12	
LASALLE-BACKUS EDUCATION CAMPUS 501 RIGGS ROAD NE	8		7
WHEATLEY EDUCATION CAMPUS 1299 NEAL STREET NE	5		1
DREW ELEMENTARY SCHOOL 5600 EADS STREET NE	7		2
CARDOZO EDUCATIONAL CAMPUS 1200 CLIFTON ST NW	1		
MARIE REED EDUCATION CAMPUS 2201 18TH ST NW	1	7	
TAKOMA EDUCATIONAL CAMPUS 7010 PINEY BRANCH RD NW	4		
SOUSA MIDDLE SCHOOL 3650 ELY PLACE SE	7		1

SOUSA MIDDLE SCHOOL 3650 ELY PLACE SE	7		1
BEERS ELEMENTARY SCHOOL 3600 ALABAMA AVENUE SE	7		12
STODDERT ELEMENTARY SCHOOL 4001 CALVERT STREET NW	3	1	
POWELL ELEMENTARY SCHOOL	4	6	12
WATKINS ELEMENTARY SCHOOL 420 12TH STREET SE	6	9	
WHITTIER ELEMENTARY SCHOOL 6201 5th St NE	4		2
STANTON ELEMENTARY SCHOOL 2701 NAYLOR RD SE	8	8	16
HEARST ELEMENTARY SCHOOL	3	1	
HENDLEY ELEMENTARY SCHOOL 425 CHESAPEAKE STREET SE	8	6	
HOUSTON ELEMENTARY SCHOOL 1100 50TH PLACE NE	7	7	
MILITARY ROAD EARLY LEARNING CENTER 1375 Missouri Avenue Northwest	4		1
HART MIDDLE SCHOOL 601 MISSISSIPPI AVENUE SE	8		1
SAVOY ELEMENTARY SCHOOL	8		16

/25/26 DCPS Cooling Contingency Plan

Barrell Fans	Reason contingencies were required	Room Numbers
	Room- A119 Contingency Hanging heater is hanging from the wall causing a safety concern. Please repair or reinstall asap	A119
	Window units and spot coolers installed throughout	A and B wing
	Classrooms B106, B210, B301, B305 & B410 needs contingency temporary cooling, all rooms are extremely hot.	B106, B210, B301, B305 & B410
	Spot Coolers are Needed in Rms- 226, 308 & 409. Serves: Classrms, Location: Main Building.	226, 308, 409
	Replace A/C window units in rooms 208 (BTU 12000 Volts 115 Amps 11.0) unit #2, room 203 (BTU 115) No information, room 205 (BTU 18000 Volts 115 Amps 11.0), room 010 (BTU 8000 Volts 115 Amps 6.9), room 009A (BTU 18000/17500 Volts 230/208 Amps 6.9/7.5.0	208, 203, 205, 010, 009A
	Install a contingency window AC unit in the kitchen, the space temperature is 90 F.	Kitchen trailer
	Please install a contingency window AC 12,000 or 14,000 BTU in the classroom; the Univent is inoperable.	2nd Floor Rm 239
	Please install Contingency units in these 12 affected rooms 304,305,310,311B,311A,315,320,323,325, 335A,339 and 335.	3rd floor classrooms
	Another temporary cooling contingency a/c window unit needs to be installed in the following classroom108, 115, 204, 308 and 313. Classroom G005 needs two units installed. A a/c widow guard needs to be installed around unit, on ground floor.	Classroom 108, 15, 204, 308, 313 and Goo5
	This room needs a window unit	Room #133
	Install a contingency window ubit. Room is large needs 2.	Art Room 4TH Floor
15	Install contingency window units. Rooms are large need 2 units	LT204, LT102, T415,T500, T411, C612, C504, C603, C101A, C304, C302, C204, C152, 1503, 1205, 1203, 1304, 2302, 3504, 3404, 3402, 3102, 3204
	Unit inoperable	CU 2 serves classrooms 301, 302, 305, 306, 308, 310, 311, 319, 321
1	Unit inoperable	CU2 serves 1st fl entrance area
	Install a contingency window unit.	A303

	Install a contingency window unit.	B310
	Please install a contingency window AC for cooling in D- building D- 101,102,103,104,107,108,111, 202,204,206,210 and B building -108	D101, D102, D103, D104,D107, D108, D111, D202, D204, D206, D210 and B building -B108
	Needs a spot cooler, by 8/22/25.	242
	Install spot coolers	D224,D225,D226,D227D228 & D229, D120- Cafeteria,
	Install spot coolers on 4th floor 4th floor	4th floor All classrooms 435, 438,425,420,415,411B,411A,410, and 405
	Unit inoperable	305 and 225
	Unit inoperable	Throughout building
	Unit inoperable	104
	Unit inoperable	principle office, welcome center, main office, front lobby rooms 103,111, 113, 105, 112
	Spot coolers have been installed , 1 Has been brought do to coil being damaged	1st floor -111,112,109,108,103,100,101,
	Unit inoperable	Nurse suite
	Please install a contingency Window AC for cooling; room 124 has no AC, and the unit ventilator is inoperable	room 124 and room 117
		120,122,112,114,main office, 200, 202,206,208,210,212,300,306,308,310,127

Date air conditioning became nonfunctional	Date contingencies were completed
8/20/2025	**Completed 8/20/2025**
8/20/2025	**Completed 8/31/2025**
8/20/2025	**Completed 8/25/2025**
8/20/2025	**Completed 8/20/2025**
8/20/2025	**Completed 8/21/2025**
8/20/2025	**Completed 8/20/2025**
8/20/2025	**Cancelled**
8/20/2025	**CANCEL, 2 and 3rd floor cooling**
8/20/2025	**Completed 8/21/2025**
8/20/2025	**Completed 8/21/2025**
8/20/2025	**After further assessment with the foreman Mr. Bradley, no unit is needed as one window unit is operational and the univent is working as well.**
8/20/2025	**R.Green requested fans completed 8/20/2025**
8/20/2025	**On Hold, repairs ongoing**
8/20/2025	**Completed 8/21/2025**
8/20/2025	**Completed 8/21/2025**

8/20/2025	**Completed 8/21/2025**
8/20/2025	**Completed 8/22/2024**
8/21/2025	Standdown unit back online
8/22/2025	**Completed 8/24/2025**
8/22/2025	**Completed 8/25/2025**
8/22/2025	**Completed 8/22/2025**
8/22/2025	**Completed 8/25/2025**
8/24/2025	**Completed 8/24/2025**
8/25/2025	**Completed 8/27/2025**
8/26/2025	**Completed 8/28/2025**
8/27/2025	**Completed 8/27/2025**
9/12/2025	**Completed 9/12/2025**
9/17/2025	**Completed 9/20/2025**